FIELD INSPECTION REPORT

				4 14 19
Date of I	nspection: C	7/12/2020 District:	- Sitamachi	
Division: - 52 tamazhi Length (km): 0.950 km.				
		Jawana Madhuban-Bh	aguwan.	
	Programme:	MAINTENANCE	0	
Package		athraha Road Id	No.:	
	f the Project:	Ongoing/Completed/Under Ma		of thos bear
Work is	a case of:	New Connectivity/Up gradation	n/ Maintenance	
SI. No.		Parameters to be checked Remarks		
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e),	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
Overall	Rating	Agreement has b	een not done	
		Satisfactory (S)	atisfactory (S)	
		Satisfactory but requires In	requires Improvement (SRI)	
		Unsatisfactory (U)		

Signature)

NAME: Briga Romjom Pas (AE)