FIELD INSPECTION REPORT

Date of Inspection:	7112.2020	District: Sitamarki
	ditamashe'	Length (km): 1.74 km
Name of the Road:	Malifeana to	Banchauri School
Scheme/Programme:	MAINTENANCE	
Package No.: 12	DUM RA	Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/U	Jp gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	- a-
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME: DINESH PRATED SINGL

Æ