## FIELD INSPECTION REPORT

Date of	Inspection: (	7/12/2020 District:	- Silamaxhi	
Division	: 5itar	nasche Length (1		
	the Road:	Sahiaxa to Patanio	(	
	Programme:	MAINTENANCE	halan estimitar a ser a mana a mont in Proposition and a service service sign any special particles are mont as a service.	
Package		Beethnaha Road Id I	Vo.:	an Loop C
Status of the Project: Ongoing/Completed/Under Maintenance - Jender - due 180000			tioned in	
Work is	a case of:	New Connectivity/Op gradation	/ Maintenance	
SI. No.		Parameters to be checked Remarks		
1.,.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No		Yes/No	
4.	Compliance History			
a)	Status of ATR's & any others			
verall R	atina	Ender has been concell	ad due to some	tioned in F
veran K	aung :	Satisfactory (S)		
		Satisfactory but requires Im	provement (SRI)	

Unsatisfactory (U)

(Signature)

NAME: Pociya Ramjan Das.