FIELD INSPECTION REPORT

Date of Inspection: 372-2020			District: Ashdry	
Division: 89Sargm-1			Length (km): 6.10 KM	
	of the Road:	Sasgram a		
Packag	e/Programme:	MAINTENANCE	Road Id No.:	_
-	of the Project:	Ongoing/Comple	ted/Under Maintenance	
	s a case of:		y/Up gradation/ Maintenance	
SI. No.	Parameters to be che		to be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4	Compliance History			(THE) HESS
a)	Status of ATR's & any others			District of the last

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NOTE- This food is under Tender Process

NAME:

Vmosn

:

DESIGNATION: JE