FIELD INSPECTION REPORT

Date of Inspection: 2-/2-2020			District: Johan		
Division: Cosgram - 1			Length (km): 2.95		
Name o	The Road: L	inle & Tara	chard Roal to grown	ly	
Scheme	Programme:	MAINTENANC	E		
Package No.:		, ,	Road Id No.:		
		The state of the s	going/Completed/Under Maintenance w Connectivity/Up gradation/ Maintenance		
Work is	a case of:				
SI. No.	Parameters		s to be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)				
g)	Compaction of flank/slope & raincuts if any				
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance History				
a)	Status of ATR	's & any others			
_					

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE - This Road Is under Tender Prosty

(Signature)

NAME: Umben

DESIGNATION: 50