FIELD INSPECTION REPORT

Date of	inspection :	3-12-2020	District: Rohypo		
Division: Salaram -1			Length (km): 3-17-Em		
Name of	the Road:	Tilother	load to Kanchenter		
Scheme/	Programme:	MAINTENAN	ICE		
Package		-	Road Id No.:		
	f the Project:		pleted/Under Maintenance vity/Up gradation/ Maintenance		
Work is	COLUMN TO SECURITION OF THE PARTY OF THE PAR		the state of the s		
SI. No.	THE PARTY OF THE P	Parameters to be checked Remai			
1.	Pavement	100000			
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavernent)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance History			1	
a)	Status of ATE	R's & any others	5		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE- This Road is under Tender Processy

(Signature)

NAME:

Umosy

DESIGNATION:

500