

# FIELD INSPECTION REPORT

Date of Inspection : 07-12-2020	District: East Champaran
Division : Sitkharina (Dhaka)	Length (km): 8.285 km
Name of the Road: Ghorasahi to Kundwa chainpur	
Scheme/Programme: MAINTENANCE	(New Maintenance policy 2018)
Package No.:	Road Id No.: 31708602030
Status of the Project: Ongoing/Completed/Under Maintenance	(work not started)
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

work not started. only sign board established

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Gopal  
07/12/2020  
(Signature)

NAME: Nand Gopal.

DESIGNATION: A.E. R.W.D Dhaka