

# FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: W. Champaran
Division : Narkatiyaganj		Length (km): 9.360 Km
Name of the Road: Sikta to Bheriherwa Road		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>ongoing</i>	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	<i>ongoing</i>
c)	Riding Quality	<i>ongoing</i>
d)	Road Camber	<i>ongoing</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>ongoing</i>
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

*Chandrales*  
07/12/20  
(Signature)

NAME: Chandrales pd

DESIGNATION: JE