FIELD INSPECTION REPORT

Division		08.12. 200	District: Samastipy	7
Name of the Book			Length (km):	
		MDR TOZ-	- Adalpyr	
Package	Programme:	MAINTENANCE		
			Road Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance		
Print The Late of Control of Control		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Property is a second
1.	Payement		Webspha 2007	Remark
a)	Road Junction condition			Manager La
b)	Condition of Surfacing			S/U
c)				S/U
	Riding Quality			S/U
d)	Road Camber			
c)	Whether free from defects such as visible cracks, exposed			S/U
f)	and the same of the Payement.			Yes/No
	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			1 65/100
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/			A STATE OF THE STA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
*3 ,	Road Furniture			S/SRI/U
			The state of the s	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/			Yes/No
4.	Compliance I			174.0324
a)	Status of ATR	's & any others	Total Control of the San Alberta Control	State Me

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI	
Unsatisfactory (U))

Work not started.

NAME: AJay Kr. Singh

DESIGNATION: J.E.

08/12/2020

AL

08/19/2020 (Signature)