

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>SAMASTIPUR</u>
Division : <u>RWD WORKS DW ROSERA</u>		Length (km):
Name of the Road: <u>Dasaut - Kakarghat</u>		
Scheme/Programme: <u>MAINTENANCE</u>		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Maintenance work is just started. G.S.B, WBM. Patch-Pot is going on.

(Signature) [Signature]
6/12/20
J.E. Sarvajyoti

NAME: Sukhit Narayan

DESIGNATION: J.E. Sarvajyoti Nagar