FIELD INSPECTION REPORT

Date of	Inspection :	3-12-2020	District: Rohlas		
Division: Game			Length (km): 4.0 KM.		
Name of	f the Road:	Pana to ch	hotka mod VIA Barkam	arkory	
Scheme	Programme:	MAINTENANC	E		
Packago			Road Id No.:		
			eted/Under Maintenance		
			ty/Up gradation/ Maintenance		
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance History			1	
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE + Submitted DPRintender Process.

(Signature)

NAME:

umesh

DESIGNATION: 7.E