

FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020	District: BHOPUR
Division : P.W.D (W) Div, ARA	Length (km): 0.800
Name of the Road: Rco Road to Bhadeyan	
Scheme/Programme:	MAINTENANCE
Package No.: PCC/BH/ARA/19/0004	Road Id No.: 10401608101
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U NA
c)	Condition of railings/slab/approach for Bridges	S/SR/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRH)	
Unsatisfactory (U)	

M. S. Chakraborty
07/12/2020
J. S. (Signature)

NAME: