

## FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Buxar</u>
Division : <u>RWD, Dumraon</u>	Length (km): <u>3.631 Km</u>
Name of the Road: <u>Brahmpur path to Renathua</u>	
Scheme/Programme:	<u>MAINTENANCE</u>
Package No.:	Road Id No.:
Status of the Project:	<u>Ongoing/Completed/Under Maintenance</u>
Work is a case of:	<u>New Connectivity/Up gradation/ Maintenance</u>

Sl. No.	Parameters to be checked	Remarks
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction condition	<u>S/U</u>
b)	Condition of Surfacing	<u>S/U</u>
c)	Riding Quality	<u>S/U</u>
d)	Road Camber	<u>S/U</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>N/A</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>N/A</u>
g)	Compaction of flank/slope & raincuts if any	<u>Yes/No</u>
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>N/A</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>N/A</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>N/A</u>
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>Yes</u>
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Akshay  
02/12/2020  
JE

km  
2/12/20  
(Signature)

NAME:

DESIGNATION: