		FIELD INSPECTION REPORT		
Date of Inspection:		10/12/2020 District: BHAGALPU	District: BHAGALPUR	
Division :		NAUGACHHIA Length (km): 5.102	Length (km): 5.102	
Name of the Road :		RED ROAD RAMNAGAR CHOWK TO US MA	CHOWK TO US MANPUR	
cheme/Programme :		Maintenance	1000000	
Package No. :		MR-N/2019-20 NAVGACHUSA/09 Road Id No.:		
Status of the Project :		Ongoing/Completed/Under Maintenace	45,497	
Work is	a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.		Parameteres to be cheeked	Remarks	
1	Pavement			
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
(c)	Raod Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Conpaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culvert including its painting.		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3	Cross Drainage			
a)	Whether sign boards/infomatory/caultionaty Boards/ km & 200m stones/Pavements roads marking are provided and maintained.		Yes/No	
4	Compliance History			
a)	Status of AT	TR's & any others	The second second second	

Overall Rating:

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

C.S. bornarded to CE-2 vide S.E. R.W.D(W) circle Bhagal Pur by Letter No. 1436 Enc. Dated - 02/12/2020

NAME: YI KASH KUMAR

DESIGNATION: JUNIOR Engineer RWD WORKS RECHEN

kharik