

FIELD INSPECTION REPORT

Date of Inspection :	5-12-20	District:	West Champaran
Division :	Narkatia gong	Length (km):	2.15 km
Name of the Road:	Madhopur to Mayje Madhopur under Josa mpa		
Scheme/Programme:	MAINTENANCE		
Package No.:	AM/WE/NAR/12/0049	Road Id No.:	31889/0322/0
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRI
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Ch
(Signature)

NAME: CHANDESHWARI PRASAD MANDAL

DESIGNATION: ASST. ENGINEER