

FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Madhepura.
Division :	Madhepura	Length (km):	6.15 K.M
Name of the Road:	Matthahi to Balam Matthahi		
Scheme/Programme:	MAINTENANCE	MR-3054 (old)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/NO N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/NO N/A
g)	Compaction of flank/slope & raincuts if any	Yes/NO N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/NO N/A
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Birendra Kumar
J.E, Madhepura.
NAME:

Birend
5/12/20.
(Signature) J.E