

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>Madhepura</u>	
Division : <u>Madhepura</u>		Length (km): <u>11.30</u>	
Name of the Road: <u>Bubhani to Kanungodhigai</u>			
Scheme/Programme:		MAINTENANCE	
Package No.: <u>9</u>		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance (<u>work not started</u>)	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	N/A
b)	Condition of Surfacing	S/U	N/A
c)	Riding Quality	S/U	N/A
d)	Road Camber	S/U	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N/A
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bhramar Kumar
A.E

NAME:

DESIGNATION:

Prakash
10/12/2020
(Signature)