

FIELD INSPECTION REPORT

Date of Inspection : 8-12-2020	District: Purbi Champaran
Division : Motihari	Length (km): 3.0 km.
Name of the Road: Chhoyadano Road to Lakhpura Phulwar R. WD. Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance <input type="checkbox"/> Not Started.	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign boards Yes/No Informatory board provided
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	Not applied
Unsatisfactory (U)	

Note:- Road work not started

8/12/2020
(Signature)

NAME: Sunil Kumar Singh.

DESIGNATION: J.E.