

FIELD INSPECTION REPORT

Inspection : 5.12.2020		District : Bhagalpur	
Location : Bhagalpur		Length (Km): 12.30 km.	
Name of the Road : mirzanhat to Nadiyama.			
Scheme / Programme : MAINTENANCE Old MR.			
Package No. : —		Road Id No. : 20703208113	
Status of the Project : ☒ Ongoing / ☐ Completed / ☐ Under Maintenance			
Work is a case of : ☒ New Connectivity / ☒ Up gradation / ☐ Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	] NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	] NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	] NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NA
4.	Compliance History		
a)	Status of ATR's & any others	NA	
Overall Rating :			
	Satisfactory (S)	] NA.	
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		

Not - This Road is taken in pmsy - a & work is ongoing at present.

NAME: Rajkishor Rajak
DESIGNATION: A.E

(Signature) 
5.12.2020
A.E

