

FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District : Bhagalpur
Division :	RWD Works Div. Nargachhia	Length (km) : 3.250
Name of the Road :	NH 31 Bagri Chowk to Choushar	
Scheme/Programme :	Maintenance	
Package No. :	MR-N/2019-20 NAVGACHHIA/09	Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked	Remarks
1	Pavement	SU
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Road Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Cross Drainage	Yes/No
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones Pavements roads marking are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

C.S forwarded to CE-2 vide S.E. RWD(W)
circle Bhagalpur by letter No. 1436 Enc.
dated - 02/12/2020

(Signature)

NAME : ANIL KUMAR

DESIGNATION : ASSISTANT ENGINEER
RWD WORKS Sub-Division
Kharik