

FIELD INSPECTION REPORT

Date of Inspection: 05/12/2020 District: Gopalganj
 Division: R.W.D. Gopalganj-2 Length (km): 12.250 Km
 Name of the Road: H.N. Bhaia to Bhagalpur
 Scheme Programme: MAIN CANAL
 Package No.: Road Id No.:
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: ☐ New Connectivity ☐ Upgradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of C.C. Pavement	Yes/No N/A
f)	Contraction Joints provided or not (C.C. Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its pointing	✓ NR13
b)	Condition of Abutment & Wing walls Slab in R.C. culverts	✓ NR13
c)	Condition of railings/slab approach for Bridges	✓ NR13
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of AIB's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (NR1)

Unsatisfactory (U)

S

—

—

(Signature)

NAME: R.C. Mandal
 DESIGNATION: J.E.