

FIELD INSPECTION REPORT

Date of Inspection : 8/12/2020		District : Katihar	
Division : Katihar		Length (Km) : 9.00 Km	
Name of the Road : Madhubani charak to Mohana chandpur			
Scheme/Programme :		Maintenance	
Package No. : MR-N/19.20/Katihar/02		Road ID No. : NEA22 000861	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked		Remarks
1).	Pavement		
a)	Road Junction condition	S/U	N.A
b)	Condition of Surfacing	S/U	N.A
c)	Riding Quality	S/U	N.A
d)	Road Camber	S/U	N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N.A
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No	N.A
2).	Cross Drainage		
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	N.A
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U	N.A
3).	Road Furniture		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No	
4).	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
	Status : Work in Progress under NMP	

Name : Mitunjay Kumar
 Designation : Junior Engineer
 RWD, Works Division, Katihar

(Signature)
 8/12/20