## FIELD INSPECTION REPORT

Date of Inspection: 9/12/20 District: Macheban.  Division: Macheban? Length (km): 0.67				
Divisio				
	of the Road:	To to sa	Length (km): 0.671	
	e/Programme:	MAINTENANCE	mmggp	
Packag			Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
WA'NE BUTTE	s a case of:	New Connectivity/U	p gradation/ Maintenance	
SL No.		Parameters to	be checked	Remarks
Î.	Payement			
a)	Road Junction condition			VS/U
b)	Condition of Surfacing			
c)	Riding Quality			√S/U
d)	Road Camber .			<b>√8/U</b>
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage	<b>)</b>		a supplied
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			Property of the speak of the
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	CRE
Unsatisfactory (U)	-/-

(Signature)

NAME: KAMLESH CHOUDHARY

DESIGNATION: CE-3
RND