FIELD INSPECTION REPORT

Date of	Inspection: 10/12/22	20.0	District: Tone	
Division: 10/12/2020		James		
Name o	f the Road: LOFI - The	1	Length (km): 2.25 /	
Scheme	Programme: MAINTEN	NANCE	and to yegina	
	No.: BR-15R-22	o I	Road Id No.:) DODUIN	211.
Status o	f the Project: Ongoing/C	Completed/	Road Id No.: 2080410. Under Maintenance	2146
Work is			gradation/ Maintenance	
SI No.	Pilin	neters to	e checked	Remarks
	Pavement			J. S. J. T. S.
a)	Road Junction condition			- \$∕U
b)	Condition of Surfacing			-S/ U
c)	Riding Quality			- 8/U
d)	Road Camber			-S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/ No
f)	Contraction Joints provided or not (CC Pavement)			YesAlo
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draining			
a)	Condition of head walls in Hume pipe culverts including its painting			_S/SRI/C
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Farniture	E almon E	TO SERVE	doc- of the trans
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			- Yes /No
4.1	recomplimate of the second		PROPERTY OF THE PROPERTY OF TH	
a)	Status of ATR's & any oth	ners	and already are effects arrestons and	NA

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U .

In Molivier (Signature)
10/12/20 AE, Laxmipus

NAME:

DESIGNATION: