

FIELD INSPECTION REPORT

Date of Inspection :	10/12/2020	District:	Jamun
Division :	Jamun	Length (km):	3.50/KM
Name of the Road:	L074 - Buihayat to Masorhandi		
Scheme/Programme:	MAINTENANCE		
Package No.:	ISRRP-50	Road Id No.:	20804102150
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'SRI'
Unsatisfactory (U)	

10/12/2020
J.E

10/12/2020
(Signature)

NAME:

DESIGNATION: