

## FIELD INSPECTION REPORT

| Date of Inspection :- 05/12/2020               |                                                                                                                      | District :- Khagaria.                      |            |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------------------|------------|
| Division :- Khagaria.                          |                                                                                                                      | Length (Km) :-                             |            |
| Name of Road :- Khagaria Gosala To Maraz Path. |                                                                                                                      |                                            |            |
| Scheme/Programme :- Old MRR                    |                                                                                                                      | Maintenance                                |            |
| Package No. :-                                 |                                                                                                                      | Road ID No. :-                             |            |
| Status of Project :- Under Maintenance         |                                                                                                                      | Ongoing/Complete/Under Maintenance         |            |
| Work is a case of :-                           |                                                                                                                      | New Connectivity/Up gradation/ Maintenance |            |
| Sl. No.                                        | Parameters to be checked                                                                                             |                                            | Remarks    |
| 1.                                             | <b>Pavement</b>                                                                                                      |                                            |            |
| a)                                             | Road Junction Condition                                                                                              |                                            | ✓S/U       |
| b)                                             | Condition of Surface                                                                                                 |                                            | ✓S/U       |
| c)                                             | Riding Quality                                                                                                       |                                            | ✓S/U       |
| d)                                             | Road Camber                                                                                                          |                                            | ✓S/U       |
| e)                                             | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         |                                            | Yes/No ✓   |
| f)                                             | Constrution Joints provided or not (CC Pavement)                                                                     |                                            | NA Yes/No  |
| g)                                             | Compaction of flank/slope & raincuts if any                                                                          |                                            | NA Yes/No  |
| 2.                                             | <b>Cross Drainage</b>                                                                                                |                                            |            |
| a)                                             | Condition of head walls in Hume pipe culverts including its painting                                                 |                                            | NA S/SRI/U |
| b)                                             | Condition of Abutment & Wing walls, Slab in RCC Culverts                                                             |                                            | NA S/SRI/U |
| c)                                             | Condition of railings/slab/approach for Bridges                                                                      |                                            | NA S/SRI/U |
| 3.                                             | <b>Road Furniture</b>                                                                                                |                                            |            |
| a)                                             | Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained |                                            | ✓Yes/No    |
| 4.                                             | <b>Compliance History</b>                                                                                            |                                            |            |
| a)                                             | Status of ATR's & any others                                                                                         |                                            | NO         |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

(Signature)

  
 05/12/2020  
 J.B.  
 Khagaria.