

FIELD INSPECTION REPORT

DATE OF INSPECTION :-		DISTRICT	SUPAUL
DIVISION :- TRIVENIGANJ		LENGTH (Km)	5.730km
NAME OF ROAD :- LO42 BISHANDUR TO YADAV TOLA			
SCHEME PROGRAMME		MAINTENANCE	
PACKAGE NO. BR-35R-085		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/Maintenance	
SL. No.	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
a	Road junction condition	✓ S/U	
b	Condition of Surface	✓ S/U	
c	Riding Quality	✓ S/U	
d	Road Camber	✓ S/U	
e	Whether free from defectssuch as visible cracks exposed aggregates in case of CC pavement	✓ Yes/No	
f	Construction Joints provided or not (CC Pavement)	✓ Yes/No	
g	Compaction of flank/ Slope & Rain cuts if any	✓ Yes/No	
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b	Condition of abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3	Road Furniture		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained	✓ Yes/No	
3	Compliance History		
a	Status of ATR's & any Others	Yes/No NA	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement	
Unsatisfactory (U)	

Signature
Surenchandra. B. S.
Name

Signature
10.12.2020