

# FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	MUZAFFARPUR
Division :	MUZAFFARPUR WEST	Length (km):	5.10 km
Name of the Road:	DAMDARPUR TO KORI GAON TAN.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S/U (SRI)	
b)	Condition of Surfacing	S/U (SRI)	
c)	Riding Quality	S/U (SRI)	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. (B.T)	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others	SRI	

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

3/12/2020  
(Signature) S.E

NAME:

DESIGNATION: