MMGSY-SC FIELD INSPECTION REPORT

Date of Inspection: 10/12/2020			District: Samartipuz	
Division: Samartipur_			Length (km): 1.500	
Name of th	e Road: Chh	atnestwar Tara 1	nadlyg vidaloy to Boware	Nala Pool
	ogramme:	MAINTENANCE		
Package No.:		Road Id No.: 32010113045		
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement		dona de la compania d La compania de la co	
a) l	Road Junction condition			,S/U
b) (Condition of Surfacing			SAU
c) :	Riding Quality			S/U
d)	Road Camber			\S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Jo	Yes/No		
g)	Compaction of	Yes/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U_MA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U - PA
3.	Road Furniture			
a)	Whether sig	gn boards/informatory/ ment road markings are	/cautionary Board/km & 200m provided and maintained	Yes/No
4.	Compliance	History 🦟 🧱	the government of the second	
a)	Status of A7	TR's & any others		NA-

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: RISHT RAJ -JZ-