

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020 District: Saranathpur
 Division: Patari Length (km): 3.120 km
 Name of the Road: T03 - Hatimpur
 Theme/Programme: MAINTENANCE PMGSY
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ☒
 Work is a case of: New Connectivity/Up gradation/ Maintenance

No.	Parameters to be checked	Remarks
1.	Pavement	
1)	Road Junction condition	☒
1)	Condition of Surfacing	S/U
	Riding Quality	☒ S/U
	Road Camber	☒ S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	☒ Yes/No
	Contraction Joints provided or not (CC Pavement)	☒ Yes/No
	Compaction of flank/slope & raincuts if any	☒ Yes/No
	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	☒ S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab/approach for Bridges	S/SRI/U
	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	☒ Yes/No
	Compliance History	
	Status of ATR's & any others	

Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature
 10.12.2020
 (Signature)

Arbind Kumar Jha.

ON: AE, RWD, Subdiv - Vidya Patinagar
 Div. Patari



Samsung Quad Camera