

FIELD INSPECTION REPORT

Date of Inspection:	10.12.2020	District:	Samaraspur
Division:	Patan	Length (km):	1.10 km
Name of the Road:	Pyave Chowk to Manghi Tola		
Theme/Programme:	MAINTENANCE MM4SY (Gen)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

No.	Parameters to be checked	Remarks
Pavement		
	Road Junction condition	✓ S/U
	Condition of Surfacing	✓ S/U
	Riding Quality	✓ S/U
	Road Camber	✓ S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
	Compaction of flank/slope & raincuts if any	Yes/No
Cross Drainage		
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
Compliance History		
	Status of ATR's & any others	

Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Arjun Kumar
10.12.2020
(Signature)

By: *Arjun Kumar*

ON: *10.12.2020*, *Subdiv. Vidyapati Nagar*
Samsung Quad Camera
and with *Di. Patan*