

FIELD INSPECTION REPORT

Date of Inspection : 10.12.2020		District: Samastipur
Division : Patna		Length (km): 0.773 km.
Name of the Road: Mulchya Sadak to Mahadali tola.		
Scheme/Programme: MAINTENANCE		MM454 (SC)
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
I. No.	Parameters to be checked	Remark.
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
Cross Drainage		
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
Compliance History		
	Status of ATR's & any others	

Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Arvind Kumar Jha
10.12.2020

(Signature)

Arvind Kumar Jha.
AE, RWD, Subdiv - Vidya Patinagar
Dist. Patna



Samastipur Road Corporation