


Sl.No: - 90

FIELD INSPECTION REPORT

Date of Inspection: 08/12/2020		District: JEHANABAD
Division:		Length (km): 7.550
Name of the Road: Repair of road from Ahobi to Athamapur Mushahani via Athamapala.		
Scheme/Programme:		MAINTENANCE
Package No:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under gradation/Maintenance	
Work is a case of:	New Connectivity/Up gradation/Maintenance	
S.N	Parameters to be checked	Remarks
1.	Payment	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No No Reincut
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls. Slab in RCC culverts.	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : - About 12% Road damage

Satisfactory (S)	✗
Satisfactory but requires improvement (SRI)	✗
Unsatisfactory (U) ✓	" U "


 Signature

NAME: Santosh K. Bhaeti
 DESIGNATION: J.E, T. Riv. Jehanabad