

FIELD INSPECTION REPORT


Date of Inspection :- 05/12/2020		District :- Khagaria	
Division :- Khagaria		Length (Km) :- 1.500 km.	
Name of Road :- Repair of Road from NH-31 Mahavir Ashan to Sonvatsa Gola Pakhahuti R60 Road.			
Scheme/Programme :- Old MR		Maintenance -	
Package No. :-		Road ID No. :-	
Status of Project :- Under maintenance		Ongoing/Complete/Under Maintenance ☒	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance ☒	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	✓S/U
b)	Condition of Surface	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ☒
f)	Construction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 05/12/2020
 Khagaria.