


FIELD INSPECTION REPORT

Date of Inspection :	10/12/20	District:	SIWAN
Division :	Maharajganj	Length (km):	0.300 km
Name of the Road:	L030 to Bhitthi Paschim Tola		
Scheme/Programme:	MAINTENANCE		
Package No.:	GTSNY		
Status of the Project:	Ongoing/Completed/Under Maintenance	Road Id No.:	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—


 10/12/20
 (Signature)

NAME: ANAND KUMAR

DESIGNATION:

A.E.

10/12/20
 MANISH KUMAR OJHA
 (J.E.)