

FIELD INSPECTION REPORT

DATE OF INSPECTION :- 09.12.2020		DISTRICT	SUPAUL
DIVISION :- TRIVENIGANJ		LENGTH (Km)	1.40 Km
NAME OF ROAD :- SH-76 Dinapatti Chowk to Sukhasini.			
SCHEME PROGRAMME		MAINTENANCE	
PACKAGE NO.		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/Maintenance	
Sl. No.	PARAMETERS TO BE CHECKED		REMARKS
1	PAVEMENT		
a	Road junction condition		✓ S/U
b	Condition of Surface		✓ S/U
c	Riding Quality		✓ S/U
d	Road Camber		✓ S/U
e	Whether free from defects such as visible cracks exposed aggregates in case of CC pavement		✓ Yes/No
f	Construction Joints provided or not (CC Pavement)		✓ Yes/No
g	Compaction of flank/ Slope & Rain cuts if any		✓ Yes/No
2	Cross Drainage		
a	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts		✓ S/SRI/U
c	Condition of railings/slab/approach for Bridges		✓ S/SRI/U
3	Road Furniture		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained		✓ Yes/No
3	Compliance History		
a	Status of ATR's & any Others		Yes/No

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement	-
Unsatisfactory (U)	-

AS
09/12/20
26

(VIKAS KUMAR SAH)

Name

09.12.2020
Signature AE.