

# FIELD INSPECTION REPORT

|                        |                                                  |              |          |
|------------------------|--------------------------------------------------|--------------|----------|
| Date of Inspection :   | 9.12.2020                                        | District:    | Siwan    |
| Division :             | Maharajganj                                      | Length (km): | 1.250 km |
| Name of the Road:      | L059 to Purab Tola                               |              |          |
| Scheme/Programme:      | MAINTENANCE                                      | GTSNY        |          |
| Package No.:           |                                                  | Road Id No.: |          |
| Status of the Project: | <del>Ongoing</del> Completed/Under Maintenance ✓ |              |          |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance       |              |          |

| Sl. No. | Parameters to be checked                                                                                             | Remarks       |
|---------|----------------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | <b>Pavement</b>                                                                                                      |               |
| a)      | Road Junction condition                                                                                              | S/U S         |
| b)      | Condition of Surfacing                                                                                               | S/U S         |
| c)      | Riding Quality                                                                                                       | S/U S         |
| d)      | Road Camber                                                                                                          | S/U S         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No Yes    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No No     |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Yes    |
| 2.      | <b>Cross Drainage</b>                                                                                                |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U } S   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U } N/A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U }     |
| 3.      | <b>Road Furniture</b>                                                                                                |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No Yes    |
| 4.      | <b>Compliance History</b>                                                                                            |               |
| a)      | Status of ATR's & any others                                                                                         |               |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME:

Anand Kumar

DESIGNATION:

A.E.

Goriyakolhi

MANISH KUMAR OJHA  
(I.E.)

(Signature)

Ahu  
7/12/20

09/12/20