FIELD INSPECTION REPORT

Date o	f Inspection : 6	9/12/20 D	istrict: SIWAN	The state of the s
Divisio		RAZGANJ L	ength (km): 0 · 2 50	KH
	of the Road:		a distance of the second secon	ावीर् स
	e/Programme:	MAINTENANCE	GTSNY	and the second s
Package No.:		ye may be a second of the seco	Road Id No.:	
and the second second	of the Project:	Ongoing/Completed/Un		ontology (1881) have legale as it to come to the language for given
	ork is a case of: New Connectivity/Up gr		the same and the s	
SI. No.	<u> </u>	Parameters to be c	hecked	Remarks
1.	Pavement			
a)	Road Junction condition			S/V
b)	Condition of Surfacing			SAS
c)	Riding Quality			SA
d).	Road Camber			S/X
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			8/SRI/M
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/W	
e)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4.	Compliance History			
1)	Status of ATR's	& any others	The Time State of the Control of the	N O

Overall Rating

Satisfactory (S)	And the second s
Satisfactory but requires Improvement (SRI)	SRT
Unsatisfactory (U)	

(Signature) A.E

NAME: Mocitanjay Kyrnar gili

DESIGNATION: A.E.

MANISH KUMAR OTHA

(1.6)