

# **FIELD INSPECTION REPORT**

|                                                     |                                                                                                                      |                          |
|-----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------|
| Date of Inspection : 10/12/20                       |                                                                                                                      | District: east Champaran |
| Division : R.W.D. Bettiah                           |                                                                                                                      | Length (km): 1.21 km     |
| Name of the Road: L-38 Balak Ramprasad to Ramprasad |                                                                                                                      |                          |
| Scheme/Programme: MAINTENANCE                       |                                                                                                                      |                          |
| Package No.:                                        |                                                                                                                      |                          |
| Status of the Project:                              | Road Id No.:                                                                                                         |                          |
| Work is a case of:                                  | Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/>                                              |                          |
|                                                     | New Connectivity/Up gradation/ Maintenance                                                                           |                          |
| Sl. No.                                             | Parameters to be checked                                                                                             |                          |
| 1.                                                  | Pavement                                                                                                             | Remarks                  |
| a)                                                  | Road Junction condition                                                                                              |                          |
| b)                                                  | Condition of Surfacing                                                                                               | ✓ S/U                    |
| c)                                                  | Riding Quality                                                                                                       | ✓ S/U                    |
| d)                                                  | Road Camber                                                                                                          | ✓ S/U                    |
| e)                                                  | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ S/U                    |
| f)                                                  | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No                 |
| g)                                                  | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No                 |
| 2.                                                  | Cross Drainage                                                                                                       | ✓ Yes/No                 |
| a)                                                  | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U                |
| b)                                                  | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ S/SRI/U                |
| c)                                                  | Condition of railings/slab/approach for Bridges                                                                      | ✓ S/SRI/U                |
| 3.                                                  | Road Furniture                                                                                                       | ✓ S/SRI/U                |
| a)                                                  | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No                 |
| 4.                                                  | Compliance History                                                                                                   |                          |
| a)                                                  | Status of ATR's & any others                                                                                         |                          |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | S |
| Unsatisfactory (U)                          |   |

*[Signature]*  
10/12/20

(Signature)

NAME:

DESIGNATION: