

# FIELD INSPECTION REPORT

|                                                           |                                                                                                                      |                       |
|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|-----------------------|
| Date of Inspection : 10.12.2020                           |                                                                                                                      | District: Samastipur  |
| Division : Patna                                          |                                                                                                                      | Length (km): 0.670 km |
| Name of the Road: PWD Sadak se Pyare hain note hain balan |                                                                                                                      | vivek                 |
| Scheme/Programme: MAINTENANCE                             |                                                                                                                      | mmgsy                 |
| Package No.:                                              | Road Id No.:                                                                                                         |                       |
| Status of the Project:                                    | Ongoing/Completed/Under Maintenance ✓                                                                                |                       |
| Work is a case of:                                        | New Connectivity/Up gradation/ Maintenance                                                                           |                       |
| Sl. No.                                                   | Parameters to be checked                                                                                             | Remarks               |
| 1.                                                        | Pavement                                                                                                             |                       |
| a)                                                        | Road Junction condition                                                                                              | ✓                     |
| b)                                                        | Condition of Surfacing                                                                                               | S/U                   |
| c)                                                        | Riding Quality                                                                                                       | S/U                   |
| d)                                                        | Road Camber                                                                                                          | S/U                   |
| e)                                                        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓                     |
| f)                                                        | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                |
| g)                                                        | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                |
| 2.                                                        | Cross Drainage                                                                                                       |                       |
| a)                                                        | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U               |
| b)                                                        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U               |
| c)                                                        | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U               |
| 3.                                                        | Road Furniture                                                                                                       |                       |
| a)                                                        | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓<br>Yes/No           |
| 4.                                                        | Compliance History                                                                                                   |                       |
| a)                                                        | Status of ATR's & any others                                                                                         |                       |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

Arbind Kumar  
10.12.2020  
(Signature)

NAME: Arbind Kumar jir.

DESIGNATION: AE, RWD, Subdiv. Vidyaapati nagar  
Div. Patna