Date	of Inspection :	10-12-2020	District: Vai Shali		
Division: - Markmar			Length (km): - O. Cooko		
Name	e of the Road: - L	oothran Road to	Kakenha Hamiddlesch	ent terk	
Scher	ne/Programme:	MAINTENANCE			
	ige No.:		Road Id No.: 315077 013	382	
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work	is a case of:	New Connectivity/L	p gradation/ Maintenance		
SI. No	Parameters to be checked		Remarks		
1.	Pavement				
a)	Road Junction condition		~8/U		
b)	Condition of Surfacing			\8/U	
c)	Riding Quality			18/U	
d)	Road Camber		\8/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			(Yes/No	
g)	Compaction of flank/slope & raincuts if any			Wes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		. S/SRI/U		
3.	Road Furniture				
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance His	story			
)	Status of ATR's & any others			No	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: BHRABOM KUMOR PROSOD DESIGNATION: Q. E. R.W. Q; Bloupur

(Signature)