

# FIELD INSPECTION REPORT

DATE OF INSPECTION :-		DISTRICT	SUPAUL
DIVISION :- TRIVENIGANJ		LENGTH (Km)	4.870Km
NAME OF ROAD :- BISHANPUR TO RAJPOUR HAT			
SCHEME PROGRAMME		MAINTENANCE	
PACKAGE NO. BR-35R-193		Road Id No. :	
STATUS OF PROJECT :		ONNGING/COMPLETED/UNDER MAINTENANCE	
Work is a case of :		New Connectivity/ Up gradation/Maintenance	
Sl. No.	PARAMERERS TO BE CHECKED		REMARKS
1	<b>PAVEMENT</b>		
a	Road junction condition		✓ S/U
b	Condition of Surface		✓ S/U
c	Riding Quality		✓ S/U
d	Road Camber		✓ S/U
e	Whether free from defectssuch as visible cracks exposed aggregates in case of CC pavement		✓ Yes/No
f	Construction Joints provided or not (CC Pavement)		✓ Yes/No
g	Compaction of flank/ Slope & Rain cuts if any		✓ Yes/No
2	<b>Cross Drainage</b>		
a	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts		✓ S/SRI/U
c	Condition of railings/slab/approach for Bridges		✓ S/SRI/U
3	<b>Road Furniture</b>		
a	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained		✓ Yes/No
3	<b>Compliance History</b>		
a	Status of ATR's & any Others		Yes/No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement	
Unsatisfactory (U)	

10/2/20  
Surenendra. P. P. L.  
Name

10.2.2020  
Signature AE  
(VIKAS KUMAR SAH)