

# FIELD INSPECTION REPORT

| Date of Inspection : 03.12.2020                                |                                                                                                                      | District: SAHARSA    |
|----------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------|
| Division : SAHARSA                                             |                                                                                                                      | Length (km): 4.50 km |
| Name of the Road: Sattarwar Goshochowk to Kandaha Surya Mandir |                                                                                                                      |                      |
| Scheme/Programme: MAINTENANCE                                  |                                                                                                                      |                      |
| Package No.: 03/MRD/18-19                                      | Road Id No.:                                                                                                         |                      |
| Status of the Project: Ongoing/Completed/Under Maintenance     |                                                                                                                      |                      |
| Work is a case of: New Connectivity/Up gradation/ Maintenance  |                                                                                                                      |                      |
| Sl. No.                                                        | Parameters to be checked                                                                                             | Remarks              |
| 1.                                                             | Pavement                                                                                                             |                      |
| a)                                                             | Road Junction condition                                                                                              | ✓S/U                 |
| * b)                                                           | Condition of Surfacing                                                                                               | S/U✓                 |
| c)                                                             | Riding Quality                                                                                                       | ✓S/U                 |
| d)                                                             | Road Camber                                                                                                          | ✓S/U                 |
| e)                                                             | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓Yes/No              |
| f)                                                             | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No              |
| g)                                                             | Compaction of flank/slope & raincuts if any                                                                          | ✓Yes/No              |
| 2.                                                             | Cross Drainage                                                                                                       |                      |
| a)                                                             | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓S/SRI/U             |
| b)                                                             | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓S/SRI/U             |
| c)                                                             | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U              |
| 3.                                                             | Road Furniture                                                                                                       |                      |
| a)                                                             | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No              |
| 4.                                                             | Compliance History                                                                                                   |                      |
| a)                                                             | Status of ATR's & any others                                                                                         |                      |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            |   |
| Satisfactory but requires Improvement (SRI) | ✓ |
| Unsatisfactory (U)                          |   |

\* 1(b) Affected by 2020 Flood.

Chauhan  
03.12.2020  
(Signature)

NAME: Ravi Shanker Kumar

DESIGNATION: Junior Engineer