

# FIELD INSPECTION REPORT

Date of Inspection :	10.12.20	District:	Buxar
Division :	Buxar	Length (km):	15.5 km
Name of the Road:	Tiger Se Dhandi via Harpur Banni		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	old MR
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>fifty year maintenance</i>		
Sl. No.	Parameters to be checked	Remarks	
1.	<b>Pavement</b>		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing <i>wmc is in progress</i>	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement) <i>N/A</i>	Yes/No	
g)	Compaction of flank/slope & raincuts if any <i>N/A</i>	Yes/No	
2.	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts <i>N/A</i>	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges <i>N/A</i>	S/SRI/U	
3.	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	<b>Compliance History</b>		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR2
Unsatisfactory (U)	

NAME:

N. K. Himanshu

DESIGNATION:

सहायक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, राजपुर

(Signature)

सहायक अभियंता  
ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, राजपुर