

# FIELD INSPECTION REPORT

Date of Inspection:	9.12.2020	District:	Madhubani
Division:	Madhubani	Length(Km):	
Name of Road:	L041 TO Khangall (P.M.G.Sy)		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	<b>Pavement</b>	✓	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	Yes/No	
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	✓ S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	<b>Road Furniture</b>		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	<b>Compliance History</b>		
a)	Status of ATR's & any others		
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			

Name: Ravi Nayan Prasad Singh  
Designation: S.E R.W.D Darbhanga circle

(Signature)

9.12.20

Scanned by CamScanner

Scanned by CamScanner