

FIELD INSPECTION REPORT

| Date of Inspection: | 3.12.20 | District: | Madhubani |
|---|--|-------------|-----------|
| Division: | Madhubani | Length(Km): | |
| Name of Road: | Kusmaul To gaur muslim tal (immasy) | | |
| Scheme/Programme: | Maintenance | | |
| Package No. | | Road Id No. | |
| Status of the Project: | Ongoing/Completed/ Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| S No. | Parameters to be Checked | Remarks | |
| 1 | Pavement | | |
| a) | Road Junction condition | S/U ✓ | |
| b) | Condition of Surfacing | S/U ✓ | |
| c) | Riding Quality | S/U ✓ | |
| d) | Road Camber | S/U ✓ | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | Yes/No ✓ | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No ✓ | |
| g) | Compaction of flank /slope & raincuts if any | Yes/No ✓ | |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U ✓ | |
| b) | Condition of Abutment & Wing walls, Slabs in RCC culverts | S/SRI/U ✓ | |
| c) | Condition of railing /slabs/ approach for Bridges | S/SRI/U ✓ | |
| 3 | Road Furniture | | |
| a) | Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained | Yes/No ✓ | |
| 3 | Compliance History | | |
| a) | Status of ATR's & any others | | |
| Overall Rating: | | | |
| Satisfactory (S) | | | |
| Satisfactory but requires Improvement (SRI) | | SRI | |
| Unsatisfactory (U) | | | |

Name: ~~S. E. R. W. D.~~ R. S. I. V. Nayan Pr Singh
Designation: S. E. R. W. D. Darbhanga Circle

(Signature)

12/12/20
9.12.20

Scanned by CamScanner

Scanned by CamScanner