

FIELD INSPECTION REPORT


Date of Inspection: 10.12.2020	District: Samastipur
Division: RWD Dalsinghsarai	Length(km): 0.700 km
Name of Road: NH103 Jogi Stahan to Kalighpur muslim Tola.	
Scheme / Programme: MAINTENANCE - MP New 2018.	
Package No:	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance <i>ongoing</i>	
Work is a case of: New Connectivity/ Up gradation/ Maintenance - <i>up gradation</i>	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	-
b)	Condition of Surfacing	-
c)	Riding Quality	-
d)	Road Camber	-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	-
f)	Constraction Joint provided or not(CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Main board fixed
4	Compliance History	
a)	Status of ATR's & any others	NO

Stipulated date of Completion is 16.9.2020 but till now not starting work. NO start.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	


 10/12/2020
 (Signature)

NAME:

DESIGNATION :

Amil Prasad
JE