

# FIELD INSPECTION REPORT

Date of Inspection: 10/12-2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 0.750 km	
Name of Road: Kahaligh pur Badub a ghar Susali Jz' kange to Jamunsi River	M. Scherdt Dalsingh	
Scheme / Programme: MAINTENANCE - M P NEW - 2018		
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - ongoing		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance - up gradation	
Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓
f)	Constraction Joint provided or not(CC Pavement)	✓
g)	Compaction of flank/slope & raincuts if any	✓
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	✓
c)	Condition of railings/slab/approach for Bridge	✓
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	mainboard fitted.
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

stipulated date of completion is 16.9.2020 but still now not starting work  
Overall Rating : Not start.

Satisfactory(S)	✓
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	✓

*[Signature]*  
(Signature)

NAME: Anil Prasad  
DESIGNATION: OD