


# FIELD INSPECTION REPORT

Date of Inspection: - 10.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.20/km
Name of Road: R.E.O Road to Bhopur ghat		
Scheme / Programme: MAINTENANCE ✓		MR No: 2018.
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance - ongoing.		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance - up gradation.
Sl. No	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction Condition	—
b)	Condition of Surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	—
f)	Constraction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
<b>3</b>	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Main board missing
<b>4</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

stipulated date of completion is 16.9.2020 but till now BT survey work not start.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

  
(Signature)

NAME:

DESIGNATION :

Anil Kumar  
JB