

FIELD INSPECTION REPORT

Date of Inspection: 10/12/2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.900/km
Name of Road: NH28 Pan Shikha to Rupali Juhural Tale		
Scheme / Programme: MAINTENANCE - MP New 18		
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance <i>ongamip</i>
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>man n pccid field</i>
4	Compliance History	
a)	Status of ATR's & any others	

Stipulated date of Completion is 19.11.2020 but till now Bot system here not start.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	<i>SRI</i>
Unsatisfactory(U)	

NAME:
DESIGNATION :

Anil Prasad
SB

10/12/2020
(Signature)